



**Document Name:** HSE-FOR-8.1.2 Job Card

**Document ID:** HSE-029

**Version Date:** 05/08/2021

**Version:** 1

**Approved:** HSM

## JOB CARD

**NO:** ZAM-KAN-012

**DATE:** 10/26/2025

**COUNTRY:** Zambia

**PROJECT:** Kansanshi

**EQUIPMENT:** testtest

**CREATED AT:** 26/10/2025, 12:36:27 PM

### Checklist Items

undefined

undefined

undefined

undefined

### Job Card Details

**Title:** Job Card for ZAM-KAN-IR-012

**Country:** Zambia

**Project:** Kansanshi

**Memo:** N/A

**Priority:** Medium

**Assigned To:** None

**Start Date:** 26/8/2025, 12:36:18 PM

**Due Date:** 26/11/2025, 12:36:23 PM

**Job Card Type:** General

**Estimated Cost:** N/A

**Estimated Labor Time:** N/A

**Linked Inspection:** ZAM-KAN-IR-012

**Linked Job Card:** None

### Cost Details

**Part & Material Cost:** 0.00

**Total Labor Cost:** 0.00

**Additional Cost:** 0.00

**Tax Amount:** 0.00 (%)

**Total WO Cost:** 0.00

## Tasks

#	Description	Type	Status	Note
1	Fix DRIP TRAY / BUNDING	Repair	Hold	Auto-generated from inspection: ZAM-KAN-IR-012
2	Fix 5 METER AWAY FROM WATER SOURCE	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-012
3	Fix FUEL TANK CAP	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-012
4	Fix EXHAUST BRACKET AND SILENCER	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-012

## Labor

#	Worker	Code	Rate	Time
No labor items available				

## Parts

#	Item No	Part No	Name	Quantity	Cost
No parts available					

## Additional Costs

#	Description	Amount
No additional costs available		

## Remarks

--	--

#	Description
No remarks available	