



Document Name: HSE-FOR-8.1.2 Job Card

Document ID: HSE-029

Version Date: 05/08/2021

Version: 1

Approved: HSM

JOB CARD

NO: ZAM-KAN-014

DATE: 10/26/2025

COUNTRY: Zambia

PROJECT: Kansanshi

EQUIPMENT: ertert

CREATED AT: 26/10/2025, 12:42:12 PM

Checklist Items

undefined

undefined

undefined

undefined

Job Card Details

Title: Job Card for ZAM-KAN-IR-011

Country: Zambia

Project: Kansanshi

Memo: N/A

Priority: Medium

Assigned To: None

Start Date: N/A

Due Date: N/A

Job Card Type: General

Estimated Cost: N/A

Estimated Labor Time: N/A

Linked Inspection: ZAM-KAN-IR-011

Linked Job Card: None

Cost Details

Part & Material Cost: 0.00

Total Labor Cost: 0.00

Additional Cost: 0.00

Tax Amount: 0.00 (%)

Total WO Cost: 0.00

Tasks

#	Description	Type	Status	Note
1	Fix 5 METER AWAY FROM WATER SOURCE	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-011
2	Fix FIRE EXTINGUISHER & SIGNAGE	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-011
3	Fix ENGINE OIL LEVEL	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-011
4	Fix PRESSURE RELIEF VALVE	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-011

Labor

#	Worker	Code	Rate	Time
No labor items available				

Parts

#	Item No	Part No	Name	Quantity	Cost
No parts available					

Additional Costs

#	Description	Amount
No additional costs available		

Remarks

--	--

#	Description
No remarks available	