



Document Name: HSE-FOR-8.1.2 Job Card

Document ID: HSE-029

Version Date: 05/08/2021

Version: 1

Approved: HSM

JOB CARD

NO: ZAM-KAN-JC-5594

DATE: 10/15/2025

COUNTRY: Zambia

PROJECT: Kansanshi

EQUIPMENT: Test Equipment 8

CREATED AT: 15/10/2025, 2:22:11 PM

Checklist Items

undefined

undefined

undefined

undefined

Job Card Details

Title: Job Card for ZAM-KAN-IR-002

Country: Zambia

Project: Kansanshi

Memo: Cc

Priority: High

Assigned To: None

Start Date: N/A

Due Date: N/A

Job Card Type: General

Estimated Cost: N/A

Estimated Labor Time: N/A

Linked Inspection: ZAM-KAN-IR-002

Linked Job Card: None

Cost Details

Part & Material Cost: 0.00

Total Labor Cost: 0.00

Additional Cost: 0.00

Tax Amount: 0.00 (%)

Total WO Cost: 0.00

Tasks

#	Description	Type	Status	Note
1	Fix 5 METER AWAY FROM WATER SOURCE	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-002
2	Fix FIRE EXTINGUISHER & SIGNAGE	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-002
3	Fix ENGINE OIL LEVEL	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-002
4	Fix RADIATOR COOLANT (IF APPLICABLE)	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-002

Labor

#	Worker	Code	Rate	Time
No labor items available				

Parts

#	Item No	Part No	Name	Quantity	Cost
No parts available					

Additional Costs

#	Description	Amount
No additional costs available		

Remarks

--	--

#	Description
No remarks available	