



Document Name: HSE-FOR-8.1.2 Job Card
Document ID: HSE-029
Version Date: 05/08/2021
Version: 1
Approved: HSM

JOB CARD

NO: ZAM-KAN-002 **DATE:** 10/15/2025 **COUNTRY:** Zambia **PROJECT:** Kansanshi
EQUIPMENT: Test Equipment 8 **CREATED AT:** 10/15/2025, 7:29:17 PM

Checklist Items

undefined

Job Card Details

Title: Job Card for ZAM-KAN-IR-003 **Country:** Zambia **Project:** Kansanshi **Memo:** rter
Priority: Medium **Assigned To:** None **Start Date:** 10/15/2025, 7:28:00 PM
Due Date: 10/31/2025, 7:28:00 PM **Job Card Type:** General **Estimated Cost:** N/A
Estimated Labor Time: N/A **Linked Inspection:** ZAM-KAN-IR-003 **Linked Job Card:** None

Cost Details

Part & Material Cost: 0.00 **Total Labor Cost:** 0.00 **Additional Cost:** 0.00 **Tax Amount:** 0.00 (%)
Total WO Cost: 0.00

Tasks

| # | Description | Type | Status | Note |
|---|-------------------------|--------|-----------|--|
| 1 | Fix DRIP TRAY / BUNDING | Repair | Initiated | Auto-generated from inspection: ZAM-KAN-IR-003 |

Labor

| # | Worker | Code | Rate | Time |
|--------------------------|--------|------|------|------|
| No labor items available | | | | |

Parts

| # | Item No | Part No | Name | Quantity | Cost |
|---|---------|---------|------|-----------|--------|
| 1 | er | ert | ret | ert Piece | ertert |

Additional Costs

| # | Description | Amount |
|-------------------------------|-------------|--------|
| No additional costs available | | |

Remarks

| # | Description |
|----------------------|-------------|
| No remarks available | |