



**Document Name:** HSE-FOR-8.1.2 Job Card

**Document ID:** HSE-029

**Version Date:** 05/08/2021

**Version:** 1

**Approved:** HSM

## JOB CARD

**NO:** ZAM-KOB-JC-4705

**DATE:** 10/15/2025

**COUNTRY:** Zambia

**PROJECT:** Kobold

**EQUIPMENT:** Test Equipment 8

**CREATED AT:** 15/10/2025, 2:45:16 PM

### Checklist Items

undefined

undefined

undefined

undefined

### Job Card Details

**Title:** Job Card for ZAM-KAN-IR-002

**Country:** Zambia

**Project:** Kobold

**Memo:** df

**Priority:** Medium

**Assigned To:** None

**Start Date:** N/A

**Due Date:** N/A

**Job Card Type:** General

**Estimated Cost:** N/A

**Estimated Labor Time:** N/A

**Linked Inspection:** ZAM-KAN-IR-002

**Linked Job Card:** None

### Cost Details

**Part & Material Cost:** 0.00

**Total Labor Cost:** 0.00

**Additional Cost:** 0.00

**Tax Amount:** 0.00 (%)

**Total WO Cost:** 0.00

Tasks

#	Description	Type	Status	Note
1	Fix 5 METER AWAY FROM WATER SOURCE	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-002
2	Fix FIRE EXTINGUISHER & SIGNAGE	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-002
3	Fix ENGINE OIL LEVEL	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-002
4	Fix RADIATOR COOLANT (IF APPLICABLE)	Repair	Initiated	Auto-generated from inspection: ZAM-KAN-IR-002

Labor

#	Worker	Code	Rate	Time
No labor items available				

Parts

#	Item No	Part No	Name	Quantity	Cost
No parts available					

Additional Costs

#	Description	Amount
No additional costs available		

Remarks

--	--

#	Description
No remarks available	