

Document Name	HSE-PRO-8.1.1 Safety Harness Inspection
Document ID	HSE-156
Version Date	01/05/2025
Version	1
Approved	HSM
Request #	DRC - MUS - HSE - 013

### **Safety Harness Checklist**

#### Safety Harness Inspection Register and Deviations

S. No.	Site	Year: 2025											
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
1													
1	Webbing										–		
2	Dirty										X		
3	Heat Damage										X		
4	Cuts or Chafing										X		
5	Seam Damaged										X		
6	Any Other Physical Damage										–		
7	Metal Loops Damaged										–		
8	Couplings Damaged										–		
9	Shackles Damaged										–		
10	Clips Damaged										–		
11	Lifeline Connections Damaged										X		
12	Lanyard Connections Damaged										–		
13	Deformation of Hook or Fittings										–		
14	Lanyard										–		
15	Lanyard Marked (Shock Absorber)										–		
16	Shock Absorber Housed Properly										–		
17	Lanyard Showing Signs of Wear										–		

Date Inspected		10/24/2025		
Initialled by the Inspector		ert		
Spot check by manager/auditor		ert		
Date spot checked		10/24/2025		
Date	Description of deviation noted	Action by whom	Target date	Complete Y/N
10/24/2025	ert	ertret	10/24/2025	N