

Document Name	HSE-FOR-8.1.1 Water Pump Prestart Check
Document ID	CA-DRC-LUB-IR-001
Version Date	10/13/2025
Version	1.0
Approved	sdf
Country	DRC
Project	Lubumbashi

## HSE-FOR-8.1.1 Water Pump Prestart Check

NO: DRC-LUB-IR-001

DATE	10/13/2025
SITE / PROJECT	Lubumbashi
INSPECTOR	sdf

COMPRESSOR No	Light vehicle-01
HOURS	6565659194 Hours

1. ALL DEFECTS UNDER "A" CLASSIFICATION TO BE ATTENDED IMMEDIATELY
2. ALL DEFECTS UNDER "B" CLASSIFICATION TO BE ATTENDED WITHIN 48 HOURS
3. ALL DEFECTS UNDER "C" CLASSIFICATION TO BE ATTENDED TO AS SOON AS POSSIBLE

DESCRIPTION	CLASS	OKAY	FAULTY	N/A	COMMENT
DRIP TRAY / BUNDING	B			—	
5 METER AWAY FROM WATER SOURCE	B		X		
REMARKS	fgh				

Overall Condition	Minor Repair required	
Vehicle Safe To Use	No	Signature: Not Provided
Maintenance Priority	Medium	

## CORRECTIVE ACTION ITEMS

Equipment Condition After Correction: Satisfactory

Role: Mechanic

Mechanic Name: fghcorrective\_action\_1760331153812\_1760338461996.pdf

Operator Name: N/A

S.No	Item	Status
1	5 METER AWAY FROM WATER SOURCE	Not Fixed

**Mechanic Signature**

A handwritten signature in black ink, consisting of a single, fluid, cursive stroke that starts with a small loop and ends with a short horizontal line.

**Operator Signature**

Not Provided