



Document Name	HSE-FOR-8.1.1 TLB Prestart Check
Document ID	CA-ZAM-KIM-IR-003
Version Date	10/13/2025
Version	1.0
Approved	sdfsdfsdf
Country	Zambia
Project	Kimteto

HSE-FOR-8.1.1 TLB Prestart Check  
NO: ZAM-KIM-IR-003

DATE	10/13/2025
SITE / PROJECT	Kimteto
INSPECTOR	sdfsdfsdf

COMPRESSOR No	Test Equipment 8
HOURS	1001 Hours

1. ALL DEFECTS UNDER "A" CLASSIFICATION TO BE ATTENDED IMMEDIATELY
2. ALL DEFECTS UNDER "B" CLASSIFICATION TO BE ATTENDED WITHIN 48 HOURS
3. ALL DEFECTS UNDER "C" CLASSIFICATION TO BE ATTENDED TO AS SOON AS POSSIBLE

DESCRIPTION	CLASS	OKAY	FAULTY	N/A	COMMENT
WORKING LIGHTS FRONT	B	✓			
WORKING LIGHTS REAR	B		X		
REMARKS	ertinput.roleName				

Overall Condition

Minor Repair required

Vehicle Safe To Use

No

Signature: Not Provided

Maintenance Priority

Medium

CORRECTIVE ACTION ITEMS

Equipment Condition After Correction: Satisfactory

Role: Operator

Mechanic Name: N/A

Operator Name: dfg

S.No	Item	Status
1	WORKING LIGHTS REAR	Not Fixed

**Mechanic Signature**

Not Provided

**Operator Signature**

A handwritten signature in black ink, consisting of a stylized 'Y' shape with a vertical line extending downwards from the center.