



Document Name	DVIR Corrective Action Report
Report ID	CA-ZAM-KAN-DVIR-007
Date	10/16/2025
Country	Zambia
Project	Kansanshi

DVIR CORRECTIVE ACTION REPORT
NO: CA-ZAM-KAN-DVIR-007

DATE	10/16/2025
SITE / PROJECT	Kansanshi

VEHICLE No	Test Equipment 8
HOURS	1007 Miles

Inspection Items

S.No	Item	Class	Okay	Faulty	N/A	Comment
Requirements						
1	I hold a valid driver's licence	A		X		
2	I will obey speed limits and road signs	A	✓			
3	I will not overload the vehicle and ensure the load is secure	A		X		
4	I have completed the vehicle pre check list and satisfied all is order for my trip	A	✓			

Corrective Action Items

Equipment Condition: Satisfactory

Role: Operator

Mechanic Name: N/A

Operator Name: ghgh

S.No	Item	Category	Status
1	I hold a valid driver's licence	Requirements	Not Fixed
2	I will not overload the vehicle and ensure the load is secure	Requirements	No Need

Mechanic Signature

Not Provided

Operator Signature